



OPC-F1-ETH Version Info

▶ 09.15.2011

Multiprotocol firmware

- No new firmware released at this time: current multiprotocol firmware is still V1.100

PROFINET firmware

- No new firmware released at this time: current PROFINET firmware is still V1.100

User's manual version

- 10764-1.100-001: principle documentation update related to RSLogix 5000 Add-On Instructions only

▶ 05.25.2011

Multiprotocol firmware

- V1.100 release
- EtherNet/IP changes
 - Added class 1 I/O support for point-to-point (unicast) in the T→O direction.
 - Fixed ListServices response to correctly return the service string.
- BACnet/IP changes
 - Fixed invalid character set for Device Object character string properties.

PROFINET firmware

- V1.100 release
- Profinet changes
 - Added support for timeout processing.

EtherNet/IP EDS file

- V2.1
- Updated connection description to support point-to-point (unicast) in the T→O direction.

User's manual version

- 10764-1.100-000

▶ 12.30.2009

Multiprotocol firmware

- V1.000 initial release.

PROFINET firmware

- V1.000 initial release.



User's manual version

- 10764-1.000-000